Head Office: 174 Cavan Road, DRY CREEK, SOUTH AUSTRALIA, 5094
Phone: +61 8 8368 0263 ~ **Fax:** +61 8 8368 0203

QLD Office: U 4 / 145 Quinns Hill Road Eacst, STAPYLTON QUEENSLAND, 4178
**Phone:** +61 7 3893 3355 ~ **Fax:** +61 7 3893 2120

ABN: 91 090 863 102   QBSA License

E-Port Wallplate Installation

To avoid causing severe damage to the E-Port Controller the installer must make certain that there is no possibility of a short circuit between any of the terminals, the charging socket and the wiring on the back of the wallplate.

Ensure that there is no swarf from the installation process, or any stray wires, that may cause a short circuit.

Also ensure that there is no possibility of the terminals shorting out against any metal in the wall that the wallplate is being installed on.

Pay particular attention to this region as any swarf may fall here.

FREECALL No: +61 1800 697 655   **Website: www.rollashield.com.au**   **Email: sales@ozroll.com.au**