

Information Bulletin 071. September 2012

Updated Multi-Fit Winder (13.112.401, 13.113.401 and 13.116.401))

As part of the ongoing product development undertaken by OZRoll an upgrade to the Multi-Fit Winder will be undertaken.

This upgrade will affect part numbers:

13.112.401 (Multi Fit Tape Winder)

13.113.401 (Multi Fit Winder with 5m of tape)

13.116.401 (Multi Fit Cord Winder)

Due to the diminishing numbers of installations using these components it has become increasingly difficult to source them, and interruptions to supply have become a regular occurrence. To ensure the availability of these components they have now been sourced through a European supplier.



This supplier is one of Europe's leading manufacturers of shutter components and produce hundreds of thousands of these winders for world wide distribution.

There will be no noticeable difference in the operation of the new winder.

There will however be some small adjustments required to the installation procedure.

Three of the four fixing hole centres are identical, and one has a slightly different alignment. If the new winder is to be used to replace an old style winder then it is recommended that the three holes that are in alignment be used. If it is a new installation there will be no issue with screw hole alignment.

The clearance holes for the screw heads on the new winder are slightly smaller than previously. To allow for this it is recommended that a screw similar to the Alkon Brand, 8gx65 Chipboard Screw (CH0865ZY) be used.