


QLD Office: U 4 / 145 Quinns Hill Road Eacst, STAPYLTON QUEENSLAND, 4178 Phone: +61 7 3893 3355 ~ Fax: +61 7 3893 2120

ABN: 91 090 863 102 QBSA License

E-Port Wallplate Installation

To avoid causing severe damage to the E-Port Controller the installer must make certain that there is no possibility of a short circuit between any of the terminals, the charging socket, and the wiring on the back of the E-Port Wallplate.

- Ensure that there is no swarf from the installation process, or any stray wires, that may cause a short circuit.
- Also ensure that there is no possibility of the terminals shorting out against any metal in the wall that the wallplate is being installed on.





Website: www.rollashield.com.au

Email: sales@ozroll.com.au