
Smoove RTS

Overview





Function Overview

Press and hold the On/Off button for 2 seconds to turn on device – the LED light will flash to indicate that device is on. Press and hold On/Off button for 2 seconds to turn off device.

Setting the 'My' position procedure is the same as the Situo range.